









x18
Ø4




LMax
K.1431.01.14 / K.1431.01.16
= 1100 [43 5/16]
K.1431.02.14 / K.1431.02.16
= 1800 [70 7/8]

mm
["]







mm
[""]




mm
[""]




1






2



3





4





mm
[""]



5 






1




2




3




4





5






6





1





2






3




4




5



6



7



Terno Scorrevoli S.p.A. Unipersonale

Via Ravenna, 4 - 20814 Varedo (MB) ITALY
Tel. +39 0362 543001 | Fax +39 0362 582290

www.ternoscorrevoli.com